ROUTINE PERFORMANCE CHECK REPORT

DataMaster DMT: 102506

Location:

Lamoille County SO

Calibration Date:

07/02/2013

Certification Date:

07/02/2013

Installation Date: RPC Date:

07/02/2013 07/02/2016

Supervisor Name:

CHRISTIAN T WATSON



Diagnostic Results

VERSIONS

DMT: 2.00

PIC: 2.05

Modem: 2.6

Ouestions: 2.1

TEMPERATURES

Sample Chamber = 49.1°C

= 48.0°C Breath Tube

Digital Sim $= 34.1^{\circ}C$

SETTINGS

Lamp Voltage = 1.78 V

Cooler Voltage = 1.77 V

Bias Voltage = 81 V

Chopper Freq = 535 Hz

PUMP INFO

Flow Rate = 4.938 L/M

DETECTOR INFO

PUMP ON

MAX(V) 0.5988 0.6008

0.5972 0.5984 MIN(V)

FILTER INFO

RUN 7/5/16 Filter 1 0.600 Zero = true

Filter 2 1.123 Zero = true

Filter 3 1.861 Zero = true

CALIBRATION CHECK

Xq = 0.087 3.63%

Routine Performance Check Passed

Accuracy and Precision Check

Concentration

= 0.098 g/210 L

Lot#

= 16-04-100 = 0.093 - 0.103

Range Average

= 0.098 g/210 L

Std Dev


=0.0005

RF Detection Test

Passed

Sample Acceptance Test

Passed



07/02/2016 Performed by Date Reviewed by Date

DMT Serial Number #102506

Page 1 of 1

07/02/2016 10:43 PM

ROUTINE PERFORMANCE CHECK REPORT

DataMaster DMT: 102506

Location:

Lamoille County SO

Calibration Date:

07/02/2013

Installation Date:

Certification Date: 07/02/2013 07/02/2013

RPC Date:

07/02/2016

Supervisor Name:

CHRISTIAN T WATSON



Diagnostic Results

VERSIONS

DMT: 2.00

PIC: 2.05

Modem: 2.6

Ouestions: 2.1

TEMPERATURES

Sample Chamber = 49.1°C

Breath Tube = 48.1°C

Digital Sim = 34.1°C

SETTINGS

Lamp Voltage = 1.78 V

Cooler Voltage = 1.77 V

Bias Voltage = 81 V

Chopper Freq = 537 Hz

PUMP INFO

Flow Rate = 4.934 L/M

DETECTOR INFO

PUMP ON

MAX(V) 0.5868

OFF 0.5878

MIN(V) 0.5850 0.5862

FILTER INFO

Filter 1 0.587 Zero = true

Filter 2 1.113 Zero = true

Filter 3 1.848 Zero = true

CALIBRATION CHECK

Xg = 0.087 3.73%

Routine Performance Check Failed

Accuracy and Precision Check

Concentration

= 0.098 g/210 L= 16-04-100

Lot#

= 0.093 - 0.103

Range

= 0.099 g/210 L

Average Std Dev

=0.0000

RF Detection Test

Failed

Performed by	cled an	_ Date _	07/02/2016	
Reviewed by		Date _		
DMT Serial Number #102506	<u>,</u>	Page 1 of 1		07/02/2016 10:30 PM

RE: June RPC

Christian Watson

Wed 7/20/2016 8:52 AM

To:Driscoll, Rob < Rob.Driscoll@vermont.gov>;

Sorry for the delay Rob, I started the 1st RPC and got called away and I I got back I hit the cancel button instead of testing the RFI

Christian Watson
Patrol Sergeant
Lamoille County Sheriff's Department
162 Commonwealth Ave
Hyde Park, VT
802-888-3502
802-279-7875 (Cell)
Christian.Watson@LamoilleSheriff.org

From: Driscoll, Rob [Rob.Driscoll@vermont.gov]

Sent: Tuesday, July 05, 2016 9:11 AM

To: Christian Watson **Subject:** June RPC

Christian,

I received your RPC, but noticed a failed attempt. Can you please give me a brief description of why the first RPC failed?

Thanks, Rob

Robert Driscoll
Vermont Forensic Laboratory
45 State Drive

Waterbury, VT 05671 Electronics Technician

[redir.aspx?

 $REF = F16QUZM6xGn2x8A1m8Salcr0iW_VNIrFTcv_elmM8dypCuOBnLDTCAFtYWlsdG86Um9iLkRyaXNjb2xsQFZlcm1$

vbnQuZ292]Rob.Driscoll@Vermont.gov

Desk: (802) 241-5817 Cell: (802) 585-0123